



FIG. NOTES

- 7 A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.

| | | |
|---|---|--|
|  | <h1>L4 HL</h1> <p>SERVICE PARTS DIAGRAM</p> | <p>Bulletin Date: Jan-18</p> |
| | <p>TTI Model Number: 016 085 005</p> <p>USB RECHARGEABLE HARD HAT HEADLAMP</p> | <p>Starting Serial Number: VERSION A - M2017</p> |

| ITEM | PART NUMBER | PART DISCRIPTION | QTY (PCS) |
|------|--------------|--|-----------|
| 1 | 016701001004 | RUBBER USB COVER | 1 |
| 2 | 016701001003 | STRAP BRACKET | 1 |
| 3 | 016701001001 | STRAP | 1 |
| 4 | 016701001002 | HARD HAT CLIP(SET OF 4) | 1 |
| 5 | 016701002005 | WALL PLUG AND MIRCO-USB CABLE (OPTIONAL) | 1 |
| 6 | 01670100201K | RATING LABEL(NOT SHOWN) | 1 |